Table of Contents

1.1 OverView 2
1.2 Reason of Upgrade 2
1.2.1 New Features 3
1.2.2 Fixed bugs 3
1.2.3 Pending Issues 3
1.3 Update Guide 3

下载时间2023-11-03 17:31:31
天地伟业技术有限公司 张玉倩

Release Notes

1.1 OverView

Item	Description
Product name	Network camera
Firmware Basic Information	Kernel Version NVSS_V30.0.1.20230527_SP2 Web Version 6.1.23.617 APP Version V4.3.0.230613.7DC3A7AB SDK Version 5.3.23.511
Related product	S6: 1D.20020.000421,1D.20020.000422 1D.20020.000423,1D.20020.000424 1D.20020.000427,1D.20020.000428 1D.20020.000429,1D.20020.000430 1D.20020.000463,1D.20020.000464 1D.20020.000465,1D.20020.000466 1D.20020.000467,1D.20020.000468 1D.20020.000469,1D.20020.000470 1D.20020.000471,1D.20020.000519 1D.20020.000520,1D.20020.000521 1D.20020.000524,1D.20020.000525 1D.20020.000526,1D.20020.000527 1D.20020.000528,1D.20020.000529 1D.20020.000530,1D.20020.000531 1D.20020.000532,1D.20020.000533 1D.20020.000534,1D.20020.000535 1D.20020.000571,1D.20020.000572 1D.20020.000575,1D.20020.000576 1D.20020.000577,1D.20020.000579 1D.20020.000581,1D.20020.000582 1D.20020.000583,1D.20020.000584 1D.20020.000616,1D.20020.000617 1D.20020.000618,1D.20020.000645 1D.20020.000646,1D.20020.000647 1D.20020.000648,1D.20020.000649 1D.20020.020060,1D.20020.020061 1D.20020.020088,1D.20020.020104 1D.20020.020102,1D.20020.020103 1D.20020.020093,1D.20020.000608 1D.20020.020135

1.2 Reason of Upgrade

Fix known defects and optimize product performance.

天地伟业技术有限公司 张玉倩
下载时间2022-11-08 17:31:21

1.2.1 New Features

None

1.2.2 Fixed bugs

1. The GPS information protocol reported by the ball machine to NVR is too long, causing NVR to restart beyond the boundary

1.2.3 Pending Issues

None

1.3 Update Guide

1. You can upgrade the Camera by Search Config Tool or web. For details, see Upgrade Guide.
2. Services such as view will be paused during the upgrade process. The Camera works normally after upgrade and rebooting.
3. The upgrade does not affect previous settings of the Camera.
4. Do not power off during the upgrade process, or the Camera will not boot up properly.

下载时间2023-11-03 17:31:31
天地伟业技术有限公司 张玉倩